

dbraun99 SU carburetor refurbishing pricing

Type	Refurbishing Price per pair	Throttle Replacement Price with Refurbishing-per pair	Throttle Replacement Price as standalone service-per pair
H Type (MG "T" series, MGA, TR3, etc.)	\$365 a pair	\$100 for replacement of std. throttle shafts and bushings	\$135 for replacement of std. throttle shafts and bushings
HS Type (MGB, MG Midget, TR4 A, Volvo etc.)	\$360 a pair	\$90 for replacement of std. throttle shafts and bushings	\$125 for replacement of std. throttle shafts and bushings
HIF Type (MGB, Volvo etc.)	\$360 a pair	\$90 for replacement of std. throttle shafts and bushings	\$125 for replacement of std. throttle shafts and bushings
HD Type (Jaguar, Big Healy, etc.)	\$375 a pair	\$100 for replacement of std. throttle shafts and bushings	\$135 for replacement of std. throttle shafts and bushings

Included in the price of the refurbishing is:

- polishing and mechanical sealing of aluminum surfaces
- jets
- metering needles
- float needles
- plating of the steel hardware in zinc (silver, nickel or Black zinc depending upon application)

Included in the price of the throttle replacement is:

- new bushings
- new shafts with belcranks installed

Refurbishing cost does not include cost of new floats; throttle disks; or replacement of parts rendered inoperable by previous attempts at rebuilding or corrosion. I will call you with a quote for these issues.

- Pricing for oversize shafts in lieu of standard shafts on HS carburetors deduct 15% from pricing shown above.
- Note: Return Shipping is included in pricing.

January 5, 2012

<http://www.dbraun99.com>
dave@dbraun99.com